

# Kingsman and Marquis Skyline II/III Gas Fireplaces recalled due to fire hazard

**Report a Concern**  
<http://www.healthycanadians.gc.ca/report-signalez/index-eng.php>

**Starting date:** April 25, 2019  
**Posting date:** April 25, 2019  
**Type of communication:** Consumer Product Recall  
**Subcategory:** Household Items, Appliances  
**Source of recall:** Health Canada  
**Issue:** Fire Hazard  
**Audience:** General Public  
**Identification number:** RA-69682

Last updated: 2019-04-25

## Summary

- **Product:** Kingsman and Marquis Skyline II/III Gas Fireplaces
- **Issue:** The affected fireplaces have a gap in the outer cabinet, which may cause nearby wood framing studs to overheat, posing a fire hazard.
- **What to do:** Immediately stop using the recalled fireplaces, shut off the gas supply to the fireplace, and contact the dealer where the fireplace was purchased to schedule a free repair.

- [Affected products](#)
- [What you should do](#)

## Affected products

### Kingsman and Marquis Skyline II/III Gas Fireplaces

#### Product description

This recall involves Kingsman Fireplaces and Marquis Collection Skyline II/III series linear gas fireplaces. The fireplaces are zero-clearance and designed for new construction applications.

The following fireplaces are included in the recall:

Fireplace Brand and Series	Model Number
Kingsman ZRB Series	ZRB46LP
	ZRB46LPE
	ZRB46N
	ZRB46NE
Kingsman VRB Series	VRB46LP
	VRB46LPE
	VRB46N
	VRB46NE
Marquis VRB Series	MQVRB46NE2

#### Hazard identified

The affected fireplaces have a gap in the outer cabinet, which may cause nearby wood framing studs to overheat, posing a fire hazard.